Monday, 15/09/2008 3:04:23 PM Date: Linda Lacelle User: **Process Sheet** : CU-DAR001 Dart Helicopters Services : REPLACEMENT GLARESHIELD KIT Customer **Drawing Name** Job Number : 42014 : 13307 **Estimate Number** P.O. Number Part Number : D412776011 : 15/09/2008 S.O. No. : : D412-776 REVB This Issue **Drawing Number** : NC : N/A Prsht Rev. **Project Number** : // : SMALL /MED FAB : B First Issue Type **Drawing Revision** : 41187 **Previous Run** Material : 16/09/2008 Qty: 1 Um: Each **Due Date** Written By Checked & Approved By Comment : Est Rev:A 08.05-12 new issue DD verified by: LL Est Rev:B 08-07-14 revB as per dwg DD verified by:ec **Additional Product** Job Number: Seq. #: Machine Or Operation: Description: 1.0 DC DOCUMENT CONTROL $\Box \Box \Box$ 08.9.16 Comment: Photocopy bluefile & type labels per PPP D412-776-011 CHG001 PACKAGING 1 2.0 PACKAGING RESOURCE #1 Comment: PACKAGING RESOURCE #1 Pick Packing Kit 3.0 D3690041 Glareshield Assembly Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Glareshield Assembly batch: 4.0 D3699041 Support Assembly Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Support Assembly batch: 5.0 D3699042 Support Assembly Comment: Qty.: 1.0000 Each(s)/Unit Total: 1.0000 Each(s) Support Assembly 41020 batch:

Date: Monday, 15/09/2008 3:04:23 PM User: Linda Lacelle **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services Drawing Name: REPLACEMENT GLARESHIELD KIT Job Number: 42014 Part Number: D412776011 Job Number: Seq. #: **Description: Machine Or Operation:** 6.0 Bolt Comment: Qty.: 6.0000 Each(s) 6.0000 Each(s)/Unit Total: Bolt batch: 7.0 AN35A Bolt Comment: Qty.: 10.0000 Each(s)/Unit Total: 10.0000 Each(s) Bolt batch: AN960JD10L Washer 8.0 Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s) Washer batch: 9.0 AN960JD6L Washer Comment: Qty.: 11.0000 Each(s)/Unit Total: 11.0000 Each(s) Washer batch: AN9703 Washers 10.0 Comment: Qty.: 4.0000 Each(s)/Unit Total: 4.0000 Each(s) Washers batch: 11.0 MS20426AD33 Rivet Comment: Qty.: 12.0000 Each(s)/Unit Total: 12.0000 Each(s) Rivet batch: MS21042L06 12.0 Nut Comment: Qty.: 11.0000 Each(s)/Unit Total: 11.0000 Each(s) Nut M10916 batch:

	tonday, 15/09/2008 3:04:23 PM inda Lacelle	Process Sheet	
Custom	er: CU-DAR001 Dart Helicopters Services	Drawing Name: REPLACEMENT GLARESHI	ELD KIT
1.1.41	Job Number: 42014 Part Number: D412776011		
Job Number:	er: 42014	Part Number: D412776011	
Seq. #:	Machine Or Operation: MS21075L08	Description:	
13.0		ANCHOR NUT	
Com		6.0000 Each(s)	<u> </u>
8	ANCHOR NUT	$() \bigcirc$	08/09/16 (x)
. 14.0	batch: M108 463 MS35206228	Screw	08/09/16 (x1)
Com	ment: Qty.: 11.0000 Each(s)/Unit Total:	11.0000 Each(s)	
ے	Screw M168963		58/09/16 XU
15.0	QC4	INSPECT 100% KITS FOR COMPLETENESS	
·			
Com 16.0	ment: INSPECT 100% KITS FOR COMPLETE PACKAGING 1	PACKAGING RESOURCE #1	16 80
→			(4)
Com	ment: PACKAGING RESOURCE #1 Identify and pack for shipping as per PP	PP D41 24 776- 0 11	
	Location: PPP Rev:	8916	90
17.0	QC21	FINAL INSPECTION/W/O RELEASE	
Com	ment: FINAL INSPECTION/W/O RELEASE		08/29/17 ff mr 08-09-16
Job Completion	1 100110 11016 1101 11016 11010 11016 11016 11016		MF 08-09-16
occ completion			,,,,